


Instruction Manual TGK001

1. Install the battery(1×CR2032)



2. Change the unit

Turn on the scale, press “UNIT” to change unit when displays zero



3. Weighing

Turn on the scale, put the item on the surface of the product when it displays zero until the data is stable. (Press the power key to zero if it doesn't display zero).



4. Tare

- (1) The weight of the weighing bowl is displayed after stabilization. Press the "Tare" button and the screen displays 0;
- (2) Put food in the bowl, the data displayed is the weight of the food;
- (3) Take off the food, then the scale is auto zero.



5. Turn off

Long press “ON/OFF” button to turn off



The product will auto turn off if there is nothing on the scale for 60 seconds;

Low battery : Lo

Overload : EEEE

